




Please note following printing error:


In the parts catalogue-no. 9550, on page 7, item 23 parts # 211109 must be parts # 211119 hinge (front cover) Please correct it in your files and inform all persons concerned to avoid any wrong orders in future. Thank you for your kind attention.

Please, also correct following on Eleft,page 6:



Item (17) with parts no 211109 is correct and item (23) with parts no 211109 has to be changed to parts no. 211311 in case of E22L and 21174 in case of E32L

Please inform all persons concerned and thank you for your kind attention.





With immediate effect is the stitchlock device available for W2600 – Series. The stitchlock device is registered as following subclass:

- 1) **SL**3J = Stitchlock device with UT3J, (pneumatic thread trimmer including pneumatic thread wiper)
- 2) **SL**4M = Stitchlock device with UT4M, (pneumatic thread trimmer with top cover thread trimmer, without thread wiper)

We are looking forward to receiving your orders.