

We would like to inform you on the discontinued models of W500 as all the standard subclasses are replaced by

W1562 and W1562/UT. Please see appended list:

W500 Discontinued model (Except Yellow highlighted items)			
Model	Japan code	Model	継続・中止
W1562-01JX356BS	R1CF3B0000000003	W562-01MCX356	DISCONTINUE
W1562-01JX356BS/UT1B	R1G93B0000000003	W562-01HBX356	DISCONTINUE
W1562-01JX356BS/UT3C	R1GD2D0000Y64903	W562-01CBX240/Y1649	DISCONTINUE
W1562-01JX356BS/UT3J	R1GD3B0000Y10503	W562-01CBX356/Y6105	DISCONTINUE
W1562-01JX356BS/UT4C	R1GF4I0000000003	W562-01DBX460	continue
W1562-01JX356BS/UT4M	R1GG2D0000000003	W562-01GBX240	DISCONTINUE
W1562-01JX364BS	R1GG3A0000000003	W562-01GBX348	continue
W1562-01JX364BS/UT1B	R1GG3B0000000003	W562-01GBX356	DISCONTINUE
W1562-01JX364BS/UT1L	R1GG3BUE00000003	W562-01GBX356/UT103	DISCONTINUE
W1562-01JX364BS/UT3J	R1GG3BV200000003	W562-01GBX356/UT303	DISCONTINUE
W1562-01JX364BS/UT4M	R1GG3BWA00000003	W562-01GBX356/UT423	DISCONTINUE
W1562-01JX232BT	R1GG3C0000000003	W562-01GBX364	DISCONTINUE
W1562-01JX240BT	R1GG3CIM00000003	W562-01GBX364/KH007A	continue
W1562-01JX240BT/UT1B	R1GG3CUEZF000003	W562-01GBX364/UT103/Z034	DISCONTINUE
W1562-01JX356CT	R1GG3CVM00000003	W562-01GBX364/UT331	DISCONTINUE
W1562-01JX356CT/UT1B	R1GG3CVMZF000003	W562-01GBX364/UT331/Z034	DISCONTINUE
W1562-01JX356CT/UT3C	R1GG3CWA00000003	W562-01GBX364/UT423	DISCONTINUE
W1562-01JX356CT/UT3J	R1GG3CZF00000003	W562-01GBX364/Z034	DISCONTINUE
W1562-01JX356CT/UT4C	R1GV3B0000000003	W562-03DBX356	DISCONTINUE
W1562-01JX356CT/UT4M	R1GV3BWA00000003	W562-03DBX356/UT423	DISCONTINUE
W1562-01JX364CT	R1GV3C0000000003	W562-03DBX364	DISCONTINUE
W1562-01JX364CT/UT1B	R1GV3CZF00000003	W562-03DBX364/Z034	DISCONTINUE
W1562-01JX364CT/UT3C	R1GX3B0000000003	W562-03EBX356	DISCONTINUE
W1562-01JX364CT/UT3J	R1HJ2EV200000003	W562-08ABX248/UT303	DISCONTINUE
W1562-01JX364CT/UT4C	R1HJ3B0000000003	W562-08ABX356	DISCONTINUE
W1562-01JX364CT/UT4M	R1HJ3BV200000003	W562-08ABX356/UT303	DISCONTINUE
W1562-02GX232BS	R1HJ3C0000000003	W562-08ABX364	DISCONTINUE
W1562-02GX232BS/TK0B→TK1C	R1HK3B0000000003	W562-08ACX356	DISCONTINUE
W1562-02GX240BS	R1HK3C0000000003	W562-08ACX364	DISCONTINUE
W1562-02GX240BS/TK0B→TK1C	R1CJ2C0000000003	W562-02GBX232	DISCONTINUE
W1562-02GX240BS/TK1B→TK3C	R1CJ2D0000000003	W562-02GBX240	DISCONTINUE
W1562-02GX248BS	R1CJ2E0000000003	W562-02GBX248	DISCONTINUE
W1562-02GX356BS	R1CJ3A0000000003	W562-02GBX348	DISCONTINUE
W1562-02GX356BS/TK1C	R1CJ3B0000000003	W562-02GBX356	DISCONTINUE
W1562-02GX356BS/TK3C	R1CJ3BTF00000003	W562-02GBX356/TK300	DISCONTINUE
W1562-02GX364BS	R1CJ3BTK00000003	W562-02GBX356/TK400	DISCONTINUE
W1562-02GX364BS/TK0B→TK1C	R1CJ3C0000000003	W562-02GBX364	DISCONTINUE
W1562-02GX364BS/TK3C	R1CJ3CZF00000003	W562-02GBX364/Z034	DISCONTINUE
W1562-05BX232BS/FT0B/MD0A	R1CK3BAU00000003	W562-02HBX356/AT310	continue
W1562-05BX240BS/FT0B/MD0A	R1CK3BAW00000003	W562-02HBX356/AT410	continue

	W500 Discontinued model (Except Yellow highlighted items)		
W1562-05BX356BS/FT0B/MD0A	R1GZ2CFAM90000003	W562-05BBX232/FT140/MD230	DISCONTINUE
W1562-05BX364BS/FT0B/MD0A	R1GZ2CFAMD0000003	W562-05BBX232/FT140/ MD441	continue
W1562-05BX232BT/FT0B/MD0A	R1GZ2DFA00000003	W562-05BBX240/FT140	?
W1562-05BX240BT/FT0B/MD0A	R1GZ2DFAM90000003	W562-05BBX240/FT140/MD230	DISCONTINUE
W1562-05BX356CT/FT0B/MD0A	R1GZ2DFAMB0000003	W562-05BBX240/FT140/ MD240	continue
W1562-05BX364CT/FT0B/MD0A	R1GZ2DFAMC0000003	W562-05BBX240/FT140/ MD440	continue
W1562-05BX364CT/FT0B/MD0A/TK3C	R1GZ2EFA00000003	W562-05BBX248/FT140	?
	R1GZ3AFA00000003	W562-05BBX348/FT140	?
	R1GZ3AFAM90000003	W562-05BBX348/FT140/MD230	DISCONTINUE
	R1GZ3BFA00000003	W562-05BBX356/FT140	?
	R1GZ3BFAM90000003	W562-05BBX356/FT140/MD230	DISCONTINUE
	R1GZ3BFAMC0000003	W562-05BBX356/FT140/ MD440	continue
	R1GZ3CFA00000003	W562-05BBX364/FT140	?
	R1GZ3CFAM90000003	W562-05BBX364/FT140/MD230	DISCONTINUE
	R1GZ3CFAM9ZF0003	W562-05BBX364/FT140/MD230/Z034	DISCONTINUE
	R1GZ3CFAZF000003	W562-05BBX364/FT140/Z034	?
	R1HB2DFAM90000003	W562-05CBX240/FT140/MD230	DISCONTINUE
	R1HB3BFAM90000003	W562-05CBX356/FT140/MD230	DISCONTINUE
	R1HB3BFAM9TK0003	W562-05CBX356/FT140/MD230/TK400	DISCONTINUE
	R1HB3BFAMB0000003	W562-05CBX356/FT140/ MD240	continue
	R1HB3CFAM90000003	W562-05CBX364/FT140/MD230	DISCONTINUE
	R1HD2CFAAU0000003	W562-05 SBX 232/FT140/ AT310	continue
	R1HD3BFAAU0000003	W562-05 SBX 356/FT140/ AT310	continue
	R1HD3BFAAUZF0003	W562-05 SBX 356/FT140/ AT310 /Z034	continue
	R1HD3BFAM9AU0003	W562-05 SBX 356/FT140/MD230/ AT310	continue
	R1HD3BFAM9AW0003	W562-05 SBX 356/FT140/MD230/ AT410	continue
	R1HD3BFAM9TH0003	W562-05 SBX 356/FT140/MD230/TK310	continue
	R1HD3CFAAUZF0003	W562-05 SBX 364/FT140/ AT310 /Z034	continue
	R1HD3CFAAYZF0003	W562-05 SBX 364/FT140/ AT710 /Z034	continue
	R1CU2CM9000000003	W562- 07 CBX232/MD230	continue
	R1HM3B00000000003	W562- 21 BAX356	continue
	R1HM3BWA000000003	W562- 21 BAX356/UT423	continue
	R1HN3B00000000003	W562- 21 BBX356	continue
	R1BA2H00000000003	W5 22-04 AX295	continue
	R1BA2HTJ000000003	W5 22-04 AX295/TK321	continue
	R1BB2G00000000003	W5 22-04 BX264	continue
	R1BB2GTJ000000003	W5 22-04 BX264/TK321	continue
	R1BB2J0000Y72303	W5 22-04 BX272/Y1723	continue
	R1CB2G00000000003	W5 22A -01FX264	continue
	R1CB2GIM000000003	W5 22A -01FX264/KH007A	continue
	R1CB2GIMP90000003	W5 22A -01FX264/KH007A/PL018	continue